

Installation Guide LSD-LED-4-8/26-840 & LSD-LED-4-8/26-850

CAUTION

- DO NOT USE OUTDOORS!
- DISCONNECT ALL POWER SOURCES BEFORE INSTALLATION.
- Equipment should be mounted in locations and at heights where it will not be tampered with.
- The use of accessory equipment is not recommended by the manufacturer, as it may cause unsafe conditions.
- Do not use the equipment for anything other than its intended use.
- This unit should be installed by a qualified electrician.
- Units must be grounded and installed in accordance with local electrical codes.
- All servicing and repairs should be performed by qualified personnel.
- All wiring must be done in compliance with local codes.



WARNING!


- ALWAYS keep AC supply off during installation
- ALWAYS keep battery unplugged during installation
- All wiring MUST be done by a licensed electrician

Sensor Installation Steps:

- 1** Screw in a motion sensor at each end




- 2** Connect the data cables



LED Module Installation Steps:


- 1** Connect DC jack from the LED module to the LED driver on the housing



- 2** Slide in the LED module



- 3** Fasten the LED module onto the housing using screws at both ends




AC Wiring (for mounting to junction box):

- 1** Remove knockout slug located at the center of housing and slide the AC cable through the created hole



- 2** With the AC cable at the other side of the housing, do the necessary wiring in a junction box



AC Diagram

Customer supplied splices.

