





Auto Repair Shop Wadsworth, IL.

BEFORE:

"The semi repair and maintenance shop had lower foot-candle levels than what is recommended by the IES (Illuminating Engineering Society). The recommended foot-candle level for a motor vehicle garage shop is anywhere from 16 to 25 foot-candles. The mechanics were having to use auxiliary lighting, which took time to set up and would clutter the area with cords and hanging lamps. Some would even hold a flashlight in their mouths to see."



230W PHOENIX LED HIGHBAYS INSTALLED (5,000K Version)



"Hey! I found sockets and tools I never even new I had in my toolbox!"

- Repair Shop Mechanic

AFTER:

"After talking to the repair shop team and listening to their grievances with the current lighting, we all came to the conclusion to just keep the original fixtures in there and add 11 of our Phoenix 230W LED Highbays. These are only 70 watts more than the current 6-lamp T8 fluorescent highbay fixtures. After installing these throughout the repair shop, the foot-candle levels increased from 49 to 76 foot-candles. Every mechanic was very happy with the outcome."

